

## **CARE & MAINTENANCE OF HOMOGENEOUS FLOORING (PUR)-**

- **Daily Cleaning:**

- Sweep or vacuum to remove dust and debris.
- Mop with neutral pH detergent and warm water.

- **Spill & Stain Management:**

- Wipe spills immediately.
- Use manufacturer-recommended cleaners for stubborn stains.

- **Periodic Maintenance:**

- Damp mop weekly.
- Apply PU/PUR polish if recommended.
- Inspect seams for wear or damage.

- **Preventive Measures:**

- Use floor mats at entrances.
- Avoid dragging heavy objects; use furniture pads.
- Maintain indoor temperature 18–27°C.

- **Long-Term Care:**

- Repair minor damages promptly.
- Regular inspection to ensure longevity (20–30 years typical).

- **Safety:**

- Ensure floor is dry after cleaning.
- Follow manufacturer's instructions for all cleaning chemicals.

## **CARE & MAINTENANCE OF STATIC DISSIPATIVE-**

- **Daily Cleaning:**

- Sweep or vacuum dust and debris.
- Mop with **neutral, ESD-safe detergent** and warm water.

- **Spill & Stain Management:**

- Wipe spills immediately to prevent damage.
- Avoid harsh chemicals (strong acids, alkalis, or solvents).

- **Periodic Maintenance:**

- Damp mop regularly (weekly or as per traffic).
- Inspect seams and conductive paths for damage.

- **Preventive Measures:**

- Use entrance mats to reduce dirt and static buildup.
- Avoid dragging heavy objects; use protective pads.
- Maintain grounding system and check electrical resistance ( $10^6$ – $10^9$   $\Omega$ ).

- **Long-Term Care:**

- Repair minor damages promptly.
- Ensure flooring remains properly grounded at all times.

- **Safety:**

- Ensure floor is dry after cleaning to prevent slips.
- Use only ESD-safe cleaning materials to maintain conductivity.